Approved For Release 2000/09/01 : CIA-RDP81B00880R000100270009-5

DPD 3108-61
24 May 1961

MEMORANDUM FOR: Chief, Special Projects Branch, DPD-DD/P

SUBJECT : Lack of ELINT Capability

25X1A REFERENCES : A. [redacted] 7390
B. [redacted] 7398

Due to the damage caused by the alternator burnout on Mission #3048 plus previous equipment damage on a similar alternator burnout about 10 May 1961, there is not sufficient ELINT collection equipment at [redacted] to support an operation. This is the fourth alternator burnout since 3 May 1961. Two of the four failures occurred on Missions (#3038 and #3048) which negated the ELINT portion of the mission effectiveness.

25X1A [redacted]
Chief, Communications Staff
DPD-DD/P

Distribution:
Orig & 1 - Addressee
1 - AC/DPD
1 - C/DPD/DB
~~1~~ - DPD/DB
1 - DPD/Logs
1 - DPD/Commo

25X1A DPD/COMMO/[redacted]:esk

10
X
2611
3/11/81

Approved For Release 2000/09/01 : CIA-RDP81B00880R000100270009-5